

Kolak, Shari

US EPA RECORDS CENTER REGION 5



501714

From: Montfort, Guy <Guy.Montfort@tetrattech.com>
Sent: Wednesday, January 13, 2016 10:48 AM
To: Madelyn.Adams@epa.ohio.gov
Cc: Kolak, Shari; Mastrolonardo, Ray
Subject: FW: Basis for no SVE testing under Church
Attachments: Current Street - former 8 to 12 East Main.png; Town Square to 12 East Main pre 1912.jpg; Gallenkamp Shoe Store - Troy 001.jpg; 8-10 East Main Sketch.docx; Current additiona.JPG; EPA Memo regarding one-hour.pdf

Hi Maddie – these were the attachments that went with Shari’s e-mail discussion she sent you on Monday regarding where the old dry cleaner was, depth of excavation, etc.

#8 – which was a 2 story building, and possibly #10 – which occupied the right half of the old 3 story building - were part of the old dry cleaner. #12 was the shoe store and it occupied the remaining part of the three story building, closest to Walnut.

8 and 10 were located where the low/single story part of the church addition roof is in the “current street” photo. 12 was about where the “tower”/2-story part of the current church addition is now and extended farther out closer to Walnut than the present structure by a few feet.

The 1912 photo shows both buildings, as well as #6 East Main, which remains much as it did in 1912. The next building to the right – toward the town square – was torn down when they built the “bank” building that is still there – now a gallery – in the 1920s I believe.

The dry cleaner operated from 1957-79. It was heavily damaged in the fire that destroyed the shoe store in September 79. It was subsequently demolished along with what was left of 10 and 12 East Main.


Thanks

Guy









[illegible]

Fig. 1

court

over